

October 29, 2019

EMERSON AUTOMATION SOLUTIONS PRODUCT SERVICE BULLETIN

Emerson Automation Solutions issued an important product service bulletin for the Crosby J-series Pressure Relief Valves on July 22, 2019.

Their evaluation shows that under certain conditions the Crosby J-series valves may have lower flow capacity. The cause for this potential non-conformance is the spring used in these valves.

PRODUCT TYPE SERIES COVERED BY THE BULLETIN

Brand: Crosby

Models: JBS-E, JLT JBS-E, JBSBP-E, JLT JBSBP-E, JBS, JLT JBS, JBSBP, JLT JBSBP

Orifice sizes: D, E, G, H, J, K, L, M, N, P, Q, R, T and T2

Production Dates: Product manufactured prior to July 22, 2019

TSASK asks owners who have the J-series Pressure Relief Valves installed on their pressure equipment to read the full [Emerson Automation Solutions Product Service Bulletin](#) for further details and service recommendations.

Your attention to this matter may prevent an unexpected and costly failure.

Chris Selinger, P.Eng.

Chief Inspector, TSASK