

February 3, 2020

## VITODENS 200-W AND VITODENS 222-F BOILERS CARBON MONOXIDE HAZARD SAFETY BULLETIN

A joint recall with Health Canada, the United States Consumer Product Safety Commission (US CPSC) and Viessmann Manufacturing Company Inc. has been issued for **Viessmann Vitodens 200-W** and **Vitodens 222-F** boiler models.

This recall involves certain Vitodens 200-W and 222-F boiler models used for space or domestic water heating. The back plate of the heat exchanger may corrode and exhaust flue gases may leak into the house or living spaces, posing a risk of increased carbon monoxide levels.

### INCLUDED IN THIS RECALL:

Product Number	Model	Part Number	Serial Numbers (Affected Range)
Vitodens 200-W	B2HB 19	7538092	7538092 <b>401003</b> 107 to 7538092 <b>701038</b> 106
	B2HB 26	7538093	7538093 <b>401002</b> 107 to 7538093 <b>701177</b> 109
	B2HB 35	7538094	7538094 <b>401003</b> 101 to 7538094 <b>701446</b> 103
Vitodens 222-F	B2TB 19	7542250	7542250 <b>401001</b> 100 to 7542250 <b>401210</b> 106
	B2TB 35	7542251	7542251 <b>401001</b> 107 to 7542251 <b>701257</b> 105

The product name and model number can be found on the left side of the boiler cover. The serial number can be found on the underside of the boiler.

Boilers which have a yellow sticker applied to the boiler rating plate located on the left side of the boiler cover have already undergone a heat exchanger replacement and are not subject to this recall.

TSASK asks owners to read the full [Consumer Product Recall](#) for further details and service recommendations.

Chris Selinger, P.Eng.  
Chief Inspector, TSASK